ID	Location Floor	Roo	m Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation	
А	pproach and Entranc	;e										
	Exterior Access Route											
1	Powers Farm Trail to Bertha Soule Memorial Park Trail		Exterior Access Route	Exterior	Exterior route	te < 48" wide	I I	Ensure that a clear width of 48" min. is maintained at the accessible route.	1	-	\$0	
2	To Play Area From Toilet Rooms		Exterior Access Route	Exterior	Surface oper Level change	•	2" A	Repair surface so that openings are 1/2" max. Alter the change in level to be 1/4" high max. Recommendation applies to all entrances to the play area.	1	-	\$0	
3	Bench Along Powers Farm Trails	I	Exterior Access Route		Does not pre	event accumulation of water	- F	Repair the surface.	1	-	\$0	
	Off-Street Parking Lo	ot or Ga	rage									
4	Parking Lot Ext.		Off-Street Parking Lot or Garage	Visitor	Total # of de	esignated accessible parking spaces esignated van accessible spaces e not provided	0 v 1 c - li - A	Provide a car accessible space 96" wide min. with a marked access aisle 60" wide min. At the car accessible space, include a sign with the International Symbol of Accessibility (ISA). At the van accessible space, include a sign with the designation "Van Accessible", with the bottom of the sign 60" min. above the ground and the top 96" max. above the ground.		-	\$0	
А	ccess to Goods and S	Service	s						<u>'</u>	,		

ID	Location	Floor Ro	oom Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation	
	Doors, Doorways, & Gates											
5	Men's Single- User Toilet Room	ct.	Doors, Doorways, & Gates	Toilet Room		Door requires > 15 lbs of force to open	17 lbs	Adjust closers so doors do not require more than 15 pounds of force to open.	1	Labor	\$0	
6	Women's Ex Single-User Toilet Room	ct.	Doors, Doorways, & Gates	Toilet Room		Door requires > 15 lbs of force to open	17 lbs	Adjust closers so doors do not require more than 15 pounds of force to open.	1	Labor	\$0	
	Operable Parts											
7	Wayside by North Main Street	ct.	Operable Parts	N/A		Element not on an accessible route	-	Locate waysides closer to the accessible route.	3	-	\$0	
8	Wayside by Pavilion	ct.	Operable Parts	N/A		Element not on an accessible route	-	Locate wayside closer to the accessible route.	1	-	\$0	
9	Book Lending Ex Library by Pavilion	ct.	Operable Parts	N/A		Element not on an accessible route	-	Locate book-lending library closer to the accessible route.	1	-	\$0	

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Picnic Tables											
10	Pavilion	Ext.	Pi	cnic Tables	N/A		Toe or knee clearance at table not provided 9" clear depth not provided	- 7.75"	Provide at least one picnic table with top between 28"- 34" above the ground, 27" clear height underneath and 19" deep.	1	-	\$0
	Benches											
11	Memorial Bench Along Powers Farm Trails	Ext.	Вє	enches	N/A		No accessible route to one bench in this area	-	Provide an accessible route to at least one bench in this area.	1	-	\$0
	Bike Racks											
12	Bike Rack	Ext.	В	ike Racks	N/A		Bike rack is not connected to an accessible route	-	Ensure bike racks are connected to an accessible route.	1	-	\$0
Т	oilet & Bathin	g Rooms										
	Overall Access											
13	Men's Single- User Toilet Room	Ext.	O	verall Access	Toilet Room		Audible and visible alarms not provided	-	When the fire system is updated, ensure that a visible and audible fire alarm is installed.	1	-	\$0

ID	Location	Floor F	Room Element	Туре	Photo	Issues	Current Measure	Recommendations Qu	uantity	Price	Cost Estimation
14	Women's Single-User Toilet Room	Ext.	Overall Access	Toilet Room		Audible and visible alarms not provided	-	When the fire system is updated, ensure that a visible and audible fire alarm is installed.	1	-	\$0
	Single-User	Toilet									
15	Women's Single-User Toilet Room	Ext.	Single-User Toilet	N/A		Inadequate maneuvering clearances	-	Relocate the trash can and cooler to provide a clear floor space that is 60" wide min. and 72" deep min.	1	-	\$0
A	dditional Acc	ess									
	Drinking Fou	ıntains									
16	Drinking Fountain Near Pavilion	Ext.	Drinking Fountains	Seated		No drinking fountain provided for standing users	-	Provide an additional drinking fountain for standing users or install a Hi-Lo drinking fountain.	1	-	\$0
Р	lay and Sport	Areas									
	Play Areas										
17	Play Area	Ext.	Play Areas	N/A		Accessible route not provided around playground	-	Install an accessible route to and around the playground.	1	-	\$0
В	est Practice		,	'			•				

ID	Location	Floor	Room Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Benches										
18	Bench Along Powers Farm Trails	Ext.	Benches	N/A			firr	ecommend providing a 36" min. by 48" min. m, stable and slip-resistant surface located ext to at least one (1) bench in this area.	1	-	\$0
19	Bench Along Bertha Soule Memorial Park Trails	Ext.	Benches	N/A			firr	ecommend providing a 36" min. by 48" min. m, stable and slip-resistant surface located ext to at least one (1) bench in this area.	1	-	\$0
20	Bench Along Powers Farm Trails	Ext.	Benches	N/A			firr	ecommend providing a 36" min. by 48" min. m, stable and slip-resistant surface located ext to at least one (1) bench in this area.	1	-	\$0
	Walkway										
21	Bertha Soule Memorial Park Trail	Ext.	Walkway	N/A				ecommend providing a railing along the alkway.	1	-	\$0